# MSE-226 Engineering Materials


**Lecture-4** 

"THERMAL PROCESSING OF METALS-2"

## CONTINUOUS COOLING TRANSFORMATION (CCT) DIAGRAMS:

☐ In industrial heat-treating operations, in most cases a steel is not isothermally transformed at a temperature above the martensite start temperature but is continuously cooled from austenitic temperature to room temperature.


#### Comparison of IT and CCT diagrams for eutectoid steel




■ No bainitic phase region in CCT diagrams of <u>plain</u> carbon steels!!!

# CONTINUOUS COOLING TRANSFORMATION (CCT) DIAGRAMS:

□ In continuously cooling a plain-carbon steel, the transformation from austenite to pearlite occurs over a range of temperatures rather than at a single isothermal temperature







#### CONTINUOUS COOLING TRANSFORMATION (CCT) DIAGRAMS: EFFECT OF ALLOYING

- 1) Alloying elements shift the austenite-to-pearlite transformation lines to longer times
- 2) A seperate bainite nose is formed

IT-diagram, 4340 steel




CCT-diagram, 4340 steel (Ni, Cr, Mn, Mo as alloying elements)



Normally, BAINITE will not form (or will form to a small extent) during continuous cooling of plain carbon steels. By alloying, it becomes possible to obtain bainite phase upon continuous cooling

#### **USE of CCT DIAGRAMS: Example**


Which microstructures do you observe upon cooling of 0.35 wt.% C iron-carbon alloy after austenitization at 850°C at different rates shown below?



- (a) Proeutectoid ferrite+fine pearlite
- (b) Martensite
- (c) Proeutectoid ferrite + martensite
- (d) Proeutectoid ferrite + coarse pearlite
- (e) Proeutectoid ferrite + pearlite + martensite

#### **TEMPERING**

#### 1) Conventional Quenching and Tempering



Altough martensite is very hard unfortunately it is very **BRITTLE** for industrial use. In order to toughen the steel and make it more ductile, a heat treatment called **tempering** is applied.


#### **Application of Tempering:**


☐ Heat the martensitic steel to a temperature below the eutectoid temperature, wait at that temperature and cool the steel at any rate.

#### **Results of tempering**

■ Ductility and toughness increases

#### **TEMPERING: The Reason of Hardness Decrease**





☐ The reason of hardness decrease upon tempering is the diffusion of carbon out of the BCT (c/a ratio decreases), (carbide precipitation)

Martensite (BCT, single phase)  $\longrightarrow$  Tempered Martensite ( $\alpha$ +Fe<sub>3</sub>C)

☐ The microstructure of tempered martensite consists of small and uniformly dispersed cementite particles within continuous ferrite matrix. The size of the cementite particles influences the mechanical behaviour of tempered martensite.

#### **TEMPERING: Tempering temperature ranges**

☐ By changing tempering parameters (temperature and time), size of the cementite particles are controlled.

#### 1) Tempering up to 200°C:

- $\square$   $\varepsilon$ -carbide(hexagonal), Fe<sub>2.4</sub>C, coherent precipitates form
- ☐ c/a ratio is still high

#### 2) Tempering above 200°C:

- $\square$   $\varepsilon$ -carbide dissolves and Fe<sub>3</sub>C appears
- ☐ When steel is tempered between 200-300°C, the shape of the precipitate is rodlike. At higher temperatures (400-700°C) the rodlike carbides coalesce to form sphere-like particles(spheroidite)

#### **Low temperature tempering (T<200°C)**

Hardness drop is small; impact toughness is relatively satisfactory


e.g. Automotive gears(case carburized+heat treated)

### High temperature tempering (400-700°C)

Hardness drop is high; improved impact toughness

e.g. Gun Barrels and all springs

#### **TEMPERING**




#### **TEMPERING: Effect of temperature and time**

#### 1) TEMPERATURE


As tempering temperature increases the rate of softening increases due to increasing of the rate of cementite particle growth.

Temperature is a diffusion controlled process so as temperature increases diffusion will be accelerated.



#### **2) TIME**

With increasing tempering time hardness decreases....



#### **SPHEROIDIZING HEAT TREATMENT**


A kind of high temperature tempering process for martensitic structures	s or
heating the pearlitic or bainitic steels to high temperatures.	

☐ Conducted to achieve minimum hardness and maximum ductility


#### □ Application:

Generally **high carbon(hypereutectoid) steels** having, pearlitic, bainitic or martensitic microstructures are heated to high temperatures below eutectoid temperature (700°C) for a sufficiently long period of time(18-24 h).

#### **SPHEROIDIZING HEAT TREATMENT**




Pearlite, partially transformed to spheroidite




**Spheroidite microstructure** 

☐ At the end of spheroidizing heat treatment cementite particles become spherical.


#### **Mechanical Properties of Spheroidite and pearlite**





#### **MARTEMPERING (Marquenching)**

☐ It is a modified quenching procedure used for steels to minimize distortion and cracking that may develop during uneven cooling of the heat treated material.



□ The effect of quenching is less drastic. Again steel is ~100% martensite. But it is more stress free so that it is more resistant to cracking and distortion.

#### Disadvantage:


Time consuming and inconvenient

#### □ Application of Martempering

Very similar to general quenching and tempering. After austenitization, the steel is quenched in hot oil or molten salt bath at a temp. slightly above  $M_s$ . Then, the steel is hold until the temperature is uniform throughout and this isothermal treatment is stopped before the austenite-to-bainite transformation begins. Finally, the part is cooled to room temperature at a moderate rate.

#### **AUSTEMPERING**

☐ It is an <u>isothermal heat treatment that produces a bainite structure</u> in some plain-carbon steels. This process provides an alternative procedure to quenching and tempering for increasing the toughness and ductility of some steels.



- □ Parts have less internal stress and more resistant to cracking and distortion but not hard and strong.
- ☐ Limited to thin and fine parts such as needles and springs

#### Application of Austempering

The steel is quenched rapidly between 250-320°C. It is soaked here for a long time.. LONG ENOUGH to produce 100% bainite. After 100% transformation, the steel is held at that temperature for a short time and then quenched to room temperature..

More gentle heating than either martempering or general tempering..

#### **ISOTHERMAL QUENCHING AND TEMPERING**

☐ Produces structure having both bainite and martensite. The steel is rapidly quenched until 50% of the austenite transformation is complete. Then it is held at this temperature for a few seconds and then heated to higher temperature to produce bainite from the remaining austenite.. The steel is soaked at this temperature for a period of time to remove internal stresses.

Between martempering and austempering

### Microstructure vs. Mechanical Properties



- Martensite
- Tempered martensite
- Bainite
- Fine pearlite
- Coarse pearlite
- Spheroidite

 Can control the formation of specific phases and microstructure so that desired properties result

